Apple II Technical Notes



Developer Technical Support

ProDOS 8

#10: Installing Clock Driver Routines

Revised by: Matt Deatherage November 1988 Revised by: Pete McDonald November 1985

This Technical Note formerly described how to install a clock driver routine other than the default.

Section 6.1.1 of the *ProDOS 8 Technical Reference Manual* documents how to install a clock driver other than the default ThunderClockTM driver or the Apple IIGS clock driver into ProDOS 8, which this Note formerly covered.

Further Reference

- ProDOS 8 Technical Reference Manual
- ProDOS 8 Technical Note #1, The GETLN Buffer and a ProDOS Clock Card